



Applies To: **2003 Accord KX 2-Door** –
From VIN 1HGCM8...3A900001 thru 1HGCM8...3A900836

September 2003

Door Window Molding Is Wrinkled

PROBLEM

The door window molding is wrinkled on one or both sides.

CORRECTIVE ACTION

Replace the affected door window molding(s).

PARTS INFORMATION

Door Molding, Left Window:
P/N 72450-SDN-A01ZA

Door Molding, Right Window:
P/N 72410-SDN-A01ZA

WARRANTY CLAIM INFORMATION

In warranty: The normal warranty applies.

Operation Number: Left, 835110
Right, 836110

Flat Rate Time: 0.4 hour, each side


Failed Part: P/N 72450-SDN-A01ZA

Defect Code: 004

Contention Code: A01

REPAIR PROCEDURE

1. Inspect both door window moldings for wrinkles.



2. Replace the door window molding(s) as needed; refer to the 2003 Accord Shop Manual.