

Applies To: **1999-02 Odyssey – ALL**
1998-02 Accord – ALL

April 2002

Clock Light Does Not Work

PROBLEM

The clock does not light up with the other instrument panel lights.

CORRECTIVE ACTION

Replace the clock illumination bulb.

PARTS INFORMATION

Clock Bulb: P/N 35505-S84-B02, H/C 5435540

WARRANTY CLAIM INFORMATION

In warranty: The normal warranty applies.

Operation Number: 715106

Flat Rate Time: 0.3 hour for Odyssey
0.2 hour for Accord


Failed Part: P/N 35505-S84-N01
H/C 5435557

Defect Code: 032

Contention Code: B01

REPAIR PROCEDURE

1. *Odyssey:* Remove the instrument panel (see procedure in the shop manual).
Accord: Remove the clock from the center panel (see procedure in the shop manual).
2. Replace the clock illumination bulb.



3. Reinstall the clock or the instrument panel.
4. Set the clock.