

Applies To: **See VEHICLES AFFECTED****July 2002**

## Front Seat Center Table Does Not Stay Up

### SYMPTOM

The front seat center table will not lock in the up position.

### PROBABLE CAUSE

The handle lock pin has sheared off.

### VEHICLES AFFECTED

2002 CR-V:

KH: From VIN JHLRD5...2C200001 thru  
JHLRD5...2C201157

KK: From VIN JHLRD6...2C200001 thru  
JHLRD6...2C200389

KQ: From VIN JHLRD7...2C200001 thru  
JHLRD7...2C205803

KX: From VIN JHLRD7...2C600001 thru  
JHLRD7...2C600606

KY: From VIN JHLRD5...2C400001 thru  
JHLRD5...2C400748

### CORRECTIVE ACTION

Replace the front seat center table.

### PARTS INFORMATION

Description	P/N	H/C
Table Assy (A/T) NH167L (Black)	81190-S9A-J03ZA	7182272
Table Assy (A/T) YR203L (Saddle)	81190-S9A-J03ZB	7182280
Left Hand Drive Table Assy (M/T) NH167L (Black)	81190-S9A-J23ZA	7182298
Left Hand Drive Table Assy (M/T) YR203L (Saddle)	81190-S9A-J23ZB	7182306
Right Hand Drive Table Assy (M/T) NH167L (Black)	81590-S9A-J23ZA	7182314
Right Hand Drive Table Assy (M/T) YR203L (Saddle)	81590-S9A-J23ZB	7182322

### WARRANTY CLAIM INFORMATION

**In warranty:** The normal warranty applies.

Operation Number: 042120

Flat Rate Time: 0.4 hour

Failed Part: P/N 81190-S9A-J01ZA  
H/C 6903611

Defect Code: 018

Contention Code: B01

### REPAIR PROCEDURE

1. Remove the front seat center table. Refer to the 2002 CR-V Shop Manual.
2. Remove the inner cover from the table. Retain the inner cover for use on the new table.
3. Install the inner cover onto the new front seat center table.
4. Install the front seat center table assembly.