

Model
1997-98
CR-V
1997
PRELUDE

Applicable To
See VEHICLES
AFFECTED

File Under



Bulletin No.

99-014

Issue Date

MAY 1999

A/C Does Not Cool Properly

SYMPTOM

The A/C does not cool well, or it does not cool at all. The temperature gauge may read high, or the vehicle may overheat. The radiator fan fuse in the under-hood fuse/relay box may also be blown.

PROBABLE CAUSE

The brushes in the radiator fan motor are contaminated.

VEHICLES AFFECTED

1997-98 CR-V – Thru VIN JHLRD1...WC004670
1997 Prelude – ALL

CORRECTIVE ACTION

Replace the radiator fan motor.

PARTS INFORMATION

Cooling Fan Motor (CR-V): P/N 19030-P3F-024
Cooling Fan Motor (Prelude): P/N 19030-P5M-004

WARRANTY CLAIM INFORMATION

The normal warranty applies.

Flat rate time: 0.3 hour
Failed part, CR-V: P/N 19030-P3F-024
Failed part, Prelude: P/N 19030-P5M-004
Defect code: 032

REPAIR PROCEDURE

1. Unplug the 2P connector from the radiator fan motor.
2. Remove the radiator fan shroud from the radiator (four bolts).
3. Remove the radiator fan from the fan motor (one nut).
4. Remove the fan motor from the fan shroud (three screws). Discard the fan motor.
5. Install the new fan motor onto the fan shroud, and secure it with the original three screws.
6. Install the radiator fan onto the fan motor shaft, and secure it with the original retaining nut. Torque the retaining nut to 4.4 N-m.
7. Reinstall the radiator fan shroud onto the radiator, and secure it with the original retaining bolts. Torque the bolts to 7 N-m.
8. Plug in the 2P connector for the fan motor.
9. If the radiator fan fuse in the under-hood fuse/relay box is blown, replace it.
10. Start the engine, and turn on the A/C. Make sure both the radiator fan and the condenser fan are running and the radiator fan is blowing air toward the engine. Check the air temperature at the dashboard vents.